PALMER


Solar Digital Pressure Gauges Model PSP100 Solar Gauge Model PSP150 Solar Gauge with Transmitter

Palmer PSP Series Solar Digital Process Pressure Gauges offer advanced technology in pressure measurement. Solar power enables the gauge to be care free when installed in various industrial applications, with no need to change batteries.

The PSP150 solar gauge with transmitter requires a current loop to provide the 4-20mA output. If loop power is removed the transmitter will stop sending 4-20mA and the gauge will draw power from it's solar cell. A gauge that will automatically power itself with solar cells when loop power is removed is a handy feature, especially in energy efficient applications.

FEATURES

- IP65 Weatherproof housing
- · ASME B40.7 Conformance
- · Transducer Based Construction
- · Rugged Shock and Vibration Resistant
- · User Selector Functions
- < 10 Lux Rating
- · Large Display
- · Model with 4-20 mA Output



Models PSP100 • PSP150 Specifications

Case: 4-1/2" (114 mm) diameter. Black Glass Reinforced Thermo Plastic (PBTP). Solid Front Construction

Blow-Out Back: Blow Out Back Safety Design, IP65 Weatherproof

Window: Acrylic

Socket/ Wetted 316SS

Sensor: Gold Plated Ceramic, Kalrez® (chemically resistant)

O-Ring Seal

Connection: Lower Connected, 1/4" NPT or 1/2" NPT

Accuracy: 0.5% Full Scale ASME 40.7 AA (.25% available, call

factory

Range Vacuum to 1,000 psi. (See Range table)

Ambient
Temperature: 10° to 140°F (-10° to 60°C)

Display: LCD with (4) 5/8" high digits

Display Lux Rating: < 10 Lux (only one foot-candle)

Display Resolution: 1/4%

Display Update: One second, Two seconds (under 20 Lux)

USER SELECTABLE FUNCTIONS

Left/Units: Select from 4 units of measure PSI, kPa, KG/CM2 or Bar with corresponding Vacuum.

Center/Zero: Adjustment ± 4 increments.


Right/Average: Set reading in average of 1, 2, 4, 8 seconds.







Pressure Gauge Models PSP100 • PSP150 Ordering Guide



Contact Customer Service for Availability and Lead-Time.

Digital Ranges								
Vacuum	PSI	kPa	KG/CM2	Bar				
30" HG*	15	100	1	1				
30" HG*	60	400	4	4				
30" HG*	100	700	7	7				
	200	1400	14	14				
	400	800	28	28				
	1000	7000	70	70				
	*Metric Reads	-100 kPa	76 CM/HG	-1 Bar				

Example of a typical pressure gauge part number configuration:

PSP100	S	L	Н	V60#	G
Model Series	Upper Connection	Mount	Lower Connection	Range/ Scale	Options

